


## EDER 3 Step Quality Control Process



- Departments responsible for the individual stages:
- 1 and 2. Logistics + Sales + Quality control
  - 3 and 4. Quality control
  - 5. Quality control
  - 6 and 7. Production + Quality Control
  - 8. Quality control
  - 9. Logistics